



## Finishing Box Tune Up

Keep your Finishing Boxes in top condition by periodically replacing the common wear parts that help you produce perfectly finished flat and butt joints. We will replace and calibrate the blade, skids, repair clips and wheels. After we've changed these parts we'll give the Finishing Box a professional cleaning, lubricate all the moving parts and adjust the tool to factory settings. This package is for EasyClean®, EasyClean® High Capacity, Power Assist®, MAXXBOX™ or Bazooka® Continuous Flow finishing boxes. The following parts will be changed as part of this Tune Up:

Quantity	Item	Description
<b>For 7" Finishing Boxes</b>		
1	200001	7" Stainless Steel Blade
2	202022	Repair Clip
1	209006	Skid Covers
1	209039	Skid Covers
2	219067	O Ring
<b>For 10" Finishing Boxes</b>		
1	250001	10" Stainless Steel Blade
2	202022	Repair Clip
1	209006	Skid Covers
1	209039	Skid Covers
2	219067	O Ring
<b>For 12" Finishing Boxes</b>		
1	300001	12" Stainless Steel Blade
2	202022	Repair Clip
1	209006	Skid Covers
1	209039	Skid Covers
2	219067	O Ring

**Price: \$74.<sup>99</sup>**  
Includes Shipping

**\$80.50 for Residents of AK or HI**  
Including FedEx 2-Day Shipping



**Important:** If your Finishing Box has other parts that are damaged or excessively worn, the Tune Up may not restore the tool to perfect working condition. Our Expert Technicians will advise you of any recommended additional repairs when the tool is examined.

**Superseded Parts Policy:** As part of our continuous product improvement, certain parts are sometimes superseded by an improved or updated part. In these cases, the actual model numbers of the parts we replace may differ from those listed in this literature but we guarantee that all the parts listed for each repair package will be replaced in regards to placement and function within the tool.

**Warranty on Repairs:** We warranty all repairs will be free from defects in parts and workmanship for a period of 1 year from the date of the repair. This applies only to the specific parts that were replaced as part of the repair.